




12	12	Flat washer M8	CPR-V1 09
11	18	Hex nut M8	CPR-V1 08
10	8	Hex bolt M8x120	CPR-V1 07
9	28	Flat washer M16	CPR-V1 06
8	16	Hex nut M16	CPR-V1 05
7	10	High tensile hex bolt (partial thread) M16x100	CPR-V1 04
6	6	Hex bolt M16x160	CPR-V1 03
5	1	Jack	CPR-V1 01
4	1	Bottom frame	CPR-V1 0000.01-A
3	1	Plate frame lower asm	CPR-V1 3000.00-A
2	1	Plate frame upper asm	CPR-V1 2000.00-A
1	2	Side frame asm	SPR-V1 1000.00-A
ITEM NO.	QTY	DESCRIPTION	PART NO.

	Machine		Description					
	Cooling Press		Cooling Press assembly					
	Projection method:		Release date	Drawing no.				
	First angle 		11/2019	CPR-V2 0000.00-B				
	General tolerances		Doc. type	Units unless specified	Sheet size	Scale	Sheet	
	ISO 2768-m		Assembly	mm	A3	1:20	1/17	